

**Dear Carrier Dealer Principal:**

With the recent implementation of ENERGY STAR efficiency requirements for ventilators in Canada, Carrier has upgraded the HRVCCSVU series of HRVs to meet the requirement. These upgrades (new fan and heat exchange core) require a part number change. Refer to Product Data Sheet HRV-04PD on HVAC Partners for complete information on the new models.

Model	Voltage	Description	Net Price
HRVXXSVU1157	115/60/1	HRV – 63-170 CFM, vertical unit with top ports	\$795

### Phase-out of HRVCCSVU1150, 1200 Model Ventilators


Due to the availability of the model shown above, Carrier is announcing the phase out of two SVU models of HRVs. For customers who have been ordering HRVCCSVU1150 and HRVCCSVU1200 units, the HRVXXSVU1157 series units will provide a close match in configuration, size and improved performance. Once the inventory of current units is depleted, orders for SVU1150 and 1200 models will no longer be accepted.

Phase Out	Description	Suggested Replacement Model
HRVCCSVU1150	HRV—150 CFM, vertical unit with top ports	HRVXXSVU1157
HRVCCSVU1200	HRV—200 CFM, vertical unit with top ports	HRVXXSVU1157

\* Orders for HRVXXSVU1157 models will not be accepted until the supply of branded models (HRVCCSVU1150 and HRVCCSVU1200) has been depleted.

Please contact your Account Manager if you have any questions.

Sincerely,



**Andy Cincar**  
**Residential Sales Manager**  
**CARRIER CANADA Central Market**



### **CARRIER CANADA CENTRAL MARKET**

**HEAD OFFICE:**  
 1515 Drew Road  
 MISSISSAUGA,  
 Ontario  
 L5S 1Y8  
 (905) 672-0606  
 FAX: (905) 405-4011

400 Parkdale Ave  
 North Units 2-4  
 HAMILTON,  
 Ontario  
 L8H5Y2  
 (905) 561-4461  
 FAX: (905) 561-3130

260 Shirley Avenue  
 KITCHENER,  
 Ontario  
 N2B 2E1  
 (519) 744-5601  
 FAX: (519) 744-2401

305-307 Consortium  
 LONDON,  
 Ontario  
 N6E 2S8  
 (519) 455-7000  
 FAX: (519) 455-7733

1050 Baxter Road  
 Baxter Road  
 OTTAWA  
 Ontario  
 K2C 3P1  
 (613) 820-7810  
 FAX: (613) 820-9462